



Conveying Granular Formulations

Dilute Phase




- •Flow as consistent density
- •High air volume requirement
- Requires metering valve
- Dusty

Dense Phase




- •Flow as slugs
- •Low air volume requirement
- •Air pressure requirement 10 40 psi
- Gentle conveyance of material

LCMCD Hopper Loading Dense Phase Pneumatic Conveyor



LCMCD Pressure Tank Loading with Granules Dilute Phase Pneumatic Conveyor



Load Cell





Sentinel Arm

